

OnSight PROS Report

Professional Documentation

The Attached Report is performed by OnSight PROS, LLC Certified Field Inspectors and thus should not be confused with an inspection performed by Licensed Real Estate Commission Inspectors. This report is an assessment of the condition of the property on the date shown and only the items listed in the report with notations made are reported on. Certified Field Inspectors are not licensed to check the mechanicals, plumbing, or electrical units in a home and therefore this report will not reflect any issues or functionality of those components. This report is for the use of the property manager and/or owner to see first hand the condition of the property address as shown on the report. If no safety issues or deficiencies are observed, NO COMMENTS will be made.



INSPECTION DATE

TECHNICIAN

INSPECTION TYPE

7/14/2016

Mr. Inspector

Move-in

PROPERTY LOCATION

123 Any Street

San Antonio, Tx 78254

PROPERTY MANAGER

Bluefax Realty

SERVICES PERFORMED

ITEM

LOCATION

Basic Property Report

NOTES

Could not locate AC unit in home.

SMELL TEST

Smell Test Performed. No exceptions noted.

Front Exterior Observed Not Applicable Attention Needed

PROPERTY DETAIL

1. Street Overview 2. Address 3. Front Left View 4. Center View 5. Front Right View 6. Driveway 7. Garage Door 8. Sidewalks 9. Yard 10. Landscaping 11. Mail Box 12. Roof/Trim 13. Walls/Siding/Trim 14. Window Screens 15. Light Fixtures 16. Other	Front Exterior	Observed	Not Applicable	Attention Needed
3 . Front Left View 4 . Center View 5 . Front Right View 6 . Driveway 7 . Garage Door 8 . Sidewalks 9 . Yard 10 . Landscaping 11 . Mail Box 12 . Roof/Trim 13 . Walls/Siding/Trim 14 . Window Screens 15 . Light Fixtures	1 . Street Overview			
4. Center View 5. Front Right View 6. Driveway 7. Garage Door 8. Sidewalks 9. Yard 10. Landscaping 11. Mail Box 12. Roof/Trim 13. Walls/Siding/Trim 14. Window Screens 15. Light Fixtures	2. Address			
5 . Front Right View 6 . Driveway 7 . Garage Door 8 . Sidewalks 9 . Yard 10 . Landscaping 11 . Mail Box 12 . Roof/Trim 13 . Walls/Siding/Trim 14 . Window Screens 15 . Light Fixtures	3. Front Left View			
6. Driveway 7. Garage Door 8. Sidewalks 9. Yard 10. Landscaping 11. Mail Box 12. Roof/Trim 13. Walls/Siding/Trim 14. Window Screens 15. Light Fixtures	4. Center View			
7. Garage Door 8. Sidewalks 9. Yard 10. Landscaping 11. Mail Box 12. Roof/Trim 13. Walls/Siding/Trim 14. Window Screens 15. Light Fixtures	5. Front Right View			
8. Sidewalks 9. Yard 10. Landscaping 11. Mail Box 12. Roof/Trim 13. Walls/Siding/Trim 14. Window Screens 15. Light Fixtures	6. Driveway			
9. Yard 10. Landscaping 11. Mail Box 12. Roof/Trim 13. Walls/Siding/Trim 14. Window Screens 15. Light Fixtures	7. Garage Door			
10 . Landscaping 11 . Mail Box 12 . Roof/Trim 13 . Walls/Siding/Trim 14 . Window Screens 15 . Light Fixtures	8 . Sidewalks			
11 . Mail Box 12 . Roof/Trim 13 . Walls/Siding/Trim 14 . Window Screens 15 . Light Fixtures	9. Yard			
12 . Roof/Trim 13 . Walls/Siding/Trim 14 . Window Screens 15 . Light Fixtures	10 . Landscaping			
13 . Walls/Siding/Trim 14 . Window Screens 15 . Light Fixtures	11. Mail Box		N/A	
14 . Window Screens 15 . Light Fixtures	12 . Roof/Trim			
15 . Light Fixtures	13 . Walls/Siding/Trim			
	14 . Window Screens			
16 . Other	15 . Light Fixtures			
	16. Other		N/A	

1 7/14/2016 4:53 PM



Street Overview Address






Front Exterior Observed Not Applicable Attention Needed

3 7/14/2016 4:55 PM



Front Left View

5 7/14/2016 4:54 PM



Front Right View

9 7/14/2016 4:54 PM



Yard

4 7/14/2016 4:53 PM



Center View

6 7/14/2016 4:54 PM



Driveway

Observed Not Applicable Attention Needed **Rear Exterior** Observed Not Applicable Rear Exterior Attention Needed 1. Rear Gate 2. Overview 3. Roof/Trim 4. Walls/Siding/Trim 5. Window Screens 6. Yard 7. Landscaping 8. Patio/Porch 9. BBQ Grill 10. Rear Door 11. Keyless Deadbolt/Pin Lock 12. Peephole 13 . Sliding Door Secondary Lock 14. Fence 15. Pet Evidence 16. Insurance Risks 17. Light Fixtures 18 . Sprinklers/Timer 19. Pool Fence

20. Other

Rear Exterior Observed Not Applicable Attention Needed

1 7/14/2016 4:55 PM



Rear Gate

2 7/14/2016 4:56 PM



Overview

8 7/14/2016 4:56 PM



Patio/Porch

1 7/14/2016 4:56 PM



Rear Gate

6 7/14/2016 4:56 PM



Yard

10 7/14/2016 4:56 PM



Rear Door

Rear Exterior Observed Not Applicable Attention Needed

11 7/14/2016 4:57 PM **12** 7/14/2016 4:57 PM



Keyless Deadbolt/Pin Lock



Peephole

Entry	Observed	Not Applicable	Attention Needed
1 . Porch/Patio			
2 . Front Door Exterior			
3. Overview (Interior)			
4 . Front Door Interior			
5. Keyless Lock/Deadbolt			
6. Peephole			
7. Floors			
8 . Ceiling			
9. Walls/Paint			
10 . Door Stops			
11 . Outlet/Switch Covers			
12 . Light Fixtures			
13. Other		N/A	
14 . Smoke Alarm SMOKE ALARM TEST: Pass ALARM TYPE: Wired			

MANUFACTURE DATE: June 2015

Observed Not Applicable Attention Needed **Entry**

7/14/2016 4:58 PM 1



Porch/Patio

7/14/2016 4:59 PM 3



Overview (Interior)

5 7/14/2016 4:59 PM



Keyless Lock/Deadbolt

2

7/14/2016 4:58 PM



Front Door Exterior

7/14/2016 4:59 PM 4



Front Door Interior

7/14/2016 4:59 PM 6



Peephole


Entry Observed Not Applicable Attention Needed

7 7/14/2016 4:59 PM



Floors

9 7/14/2016 4:59 PM



Walls/Paint

8

7/14/2016 4:59 PM



Ceiling

14 7/14/2016 5:00 PM



Smoke Alarm

Family Room	Observed	Not Applicable	Attention Needed
1 . Overview			
2 . Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops		N/A	
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			

7/14/2016 5:22 PM

9 . Light Fixture

10 . Ceiling Fan

11 . Other

12 . Smoke Alarm

2

1 7/14/2016 5:22 PM

13. Miscellaneous Issues



Overview

3



7/14/2016 5:22 PM

Ceiling



Flooring

4 7/14/2016 5:22 PM



Walls/Paint

Family Room Observed Not Applicable Attention Needed

4 7/14/2016 5:22 PM **4** 7/14/2016 5:22 PM





Walls/Paint Walls/Paint

Living Room	Observed	Not Applicable	Attention Needed
1. Overview			
2 . Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops		N/A	
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			
9 . Light Fixture			
10 . Ceiling Fan		N/A	
11. Other		N/A	
12 . Smoke Alarm		N/A	

Living Room Observed Not Applicable Attention Needed

1 7/14/2016 5:06 PM



Overview

3 7/14/2016 5:06 PM



Ceiling

4 7/14/2016 5:06 PM



Walls/Paint

2 7/14/2016 5:06 PM



Flooring

4 7/14/2016 5:06 PM



Walls/Paint

4 7/14/2016 5:06 PM



Walls/Paint

Dining Room

Observed

Observed

Not Applicable

Not Applicable

Attention Needed

Attention Needed

Dining Room

- 1. Overview
- 2. Flooring
- 3. Ceiling
- 4. Walls/Paint
- 5. Door Stops
- 6. Windows
- 7. Blinds/Drapes
- 8. Outlet/Switch Covers
- 9. Light Fixture
- 10 . Ceiling Fan
- 11. Other
- 12. Smoke Alarm

































7/14/2016 5:05 PM



2

7/14/2016 5:05 PM



Flooring

1

Dining Room Observed Not Applicable Attention Needed

3 7/14/2016 5:05 PM



Ceiling

4 7/14/2016 5:05 PM



Walls/Paint

4 7/14/2016 5:06 PM



Walls/Paint

4 7/14/2016 5:05 PM



Walls/Paint

4 7/14/2016 5:06 PM



Walls/Paint

Dining Room 2

Observed

Not Applicable

Attention Needed

Dining Room 2

- 1. Overview
- 2. Flooring
- 3. Ceiling
- 4. Walls/Paint
- 5. Door Stops
- 6. Windows
- 7. Blinds/Drapes
- 8. Outlet/Switch Covers
- 9. Light Fixture
- 10 . Ceiling Fan
- 11. Other
- 12. Smoke Alarm
- 13. Miscellaneous Issues

Observed

Not Applicable

Attention Needed

- N/A
- - N/A
 - N/A
 - N/A

1 7/14/2016 5:07 PM



2

7/14/2016 5:07 PM



Flooring

Dining Room 2

Observed

Not Applicable

Attention Needed

7/14/2016 5:07 PM

7/14/2016 5:07 PM 3



4




Walls/Paint

Ceiling

4

7/14/2016 5:07 PM



Walls/Paint

Kitchen	Observed	Not Applicable	Attention Needed
1 . Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5. Sink/Faucet			
6. Cabinet Under Sink			
7. Garbage Disposal			
8 . Range/Cooktop/Oven MANUFACTURER: Whirlpool			

Kitch	en	Observed	d Not Applicable	Attention Needed
	9. Oven MANUFACTURER: Whirlpool	✓		
	10 . Microwave Oven MANUFACTURER: Whirlpool	V		
	11 . Dishwasher MANUFACTURER: Whirlpool	V		
	12 . Refrigerator			
	13 . Lower Cabinets			
	14 . Counter Top/Back Splash			
	15 . Upper Cabinets	\checkmark		
	16 . Pantry	\checkmark		
	17 . Door Stops		N/A	
	18 . Windows		N/A	
	19 . Blinds/Drapes		N/A	
	20 . Outlet/Switch Covers	\checkmark		
	21 . Light Fixture	\checkmark		
	22 . Other		N/A	
	23 . Smoke Alarm		N/A	
1	7/14/2016 5:07 PM	2		7/14/2016 5:07 PM





Flooring

Overview

3 7/14/2016 5:08 PM



Ceiling

6 7/14/2016 5:08 PM



Cabinet Under Sink

9 7/14/2016 5:08 PM



Oven

5

7/14/2016 5:08 PM



Sink/Faucet

8 7/14/2016 5:08 PM



Range/Cooktop/Oven

9 7/14/2016 5:09 PM



Oven

10 7/14/2016 5:09 PM



Microwave Oven

11 7/14/2016 5:09 PM



Dishwasher

12 7/14/2016 5:10 PM



Refrigerator

10 7/14/2016 5:09 PM



Microwave Oven

11 7/14/2016 5:10 PM



Dishwasher

12 7/14/2016 5:10 PM



Refrigerator

13 7/14/2016 5:10 PM



Lower Cabinets

13 7/14/2016 5:11 PM



Lower Cabinets

15 7/14/2016 5:12 PM



Upper Cabinets

13 7/14/2016 5:11 PM




Lower Cabinets

13 7/14/2016 5:11 PM



Lower Cabinets

15 7/14/2016 5:12 PM



Upper Cabinets

15 7/14/2016 5:13 PM



Upper Cabinets

Garage	Observed	Not Applicable	Attention Needed
1 . Passage Door Keyless Locks/Deadbolt			
2. Passage Door Peephole			
3. Door Stops			
4. Overview			
5 . Flooring			
6. Ceiling			
7. Walls/Paint			
8 . Garage Door			
9. Garage Door Sliding Locks			
10 . Garage Door Electric Opener			
11. Windows		N/A	
12 . Blinds/Drapes		N/A	
13 . Outlet/Switch Covers			
14 . Light Fixture			
15 . Water Softener System			
16 . Interior of Brine Tank			
17. Other		N/A	

N/A

Garage Observed Not Applicable Attention Needed

18 . Smoke Alarm

1 7/14/2016 5:15 PM



Passage Door Keyless Locks/Deadbolt

4 7/14/2016 5:16 PM



Overview

2 7/14/2016 5:15 PM



Passage Door Peephole


5 7/14/2016 5:16 PM



Flooring

Garage Observed Not Applicable Attention Needed

6 7/14/2016 5:16 PM



Ceiling

7 7/14/2016 5:16 PM



Walls/Paint

16 7/14/2016 5:17 PM



Interior of Brine Tank



Walls/Paint

7 7/14/2016 5:16 PM



Walls/Paint

Observed

Observed

Not Applicable

Attention Needed

Attention Needed

Hallway/Stairway

- 1. Overview
- 2. Flooring
- 3. Ceiling
- 4. Walls/Paint
- 5. Outlet/Switch Covers
- 6. Light Fixture
- 7. Railings
- 8. Other
- 9. Smoke Alarm

SMOKE ALARM TEST: Pass

ALARM TYPE: Wired

MANUFACTURE DATE: June 2015

Not Applicable


















1


7/14/2016 5:17 PM

2

7/14/2016 5:17 PM



Overview



Flooring

Hallway/Stairway Observed Not Applicable Attention Needed

3 7/14/2016 5:17 PM



Ceiling

9 7/14/2016 5:25 PM





Smoke Alarm			
Hallway/Stairway 2	Observed	Not Applicable	Attention Needed
1 . Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5. Outlet/Switch Covers			
6 . Light Fixture			
7. Railings		N/A	
8. Other		N/A	

Attention Needed

Hallway/Stairway 2 Observed Not Applicable

9. Smoke Alarm

SMOKE ALARM TEST: Pass ALARM TYPE: Wired

MANUFACTURE DATE: June 2015

1 7/14/2016 5:32 PM **2** 7/14/2016 5:32 PM



Overview

3 7/14/2016 5:32 PM



Ceiling



Flooring

9 7/14/2016 5:33 PM




Smoke Alarm

Bathroom 2	Observed	Not Applicable	Attention Needed
1 . Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Sink/Faucet			
6 . Cabinet Under Sink			

1

Bathroom 2	Observed	Not Applicable	Attention Needed
7. Commode			
8 . Tub/Fixture		N/A	
9 . Shower/Fixture		N/A	
10 . Door Stops			
11 . Towel Bars			
12 . Window		N/A	
13 . Blinds/Drapes		N/A	
14 . Outlet/Switch Covers			
15 . Light Fixtures			
16 . Exhaust Fan			
17. Other		N/A	
18 . Smoke Alarm		N/A	



Overview Flooring

7/14/2016 5:18 PM

Bathroom 2 Observed Not Applicable Attention Needed

3 7/14/2016 5:18 PM



Ceiling

5 7/14/2016 5:18 PM



Sink/Faucet

7 7/14/2016 5:39 PM



Commode



Walls/Paint

6 7/14/2016 5:19 PM



Cabinet Under Sink

Observed Not Applicable Attention Needed Bathroom 3 Bathroom 3 Observed Not Applicable Attention Needed 1. Overview 2. Flooring 3. Ceiling 4. Walls/Paint 5. Sink/Faucet 6. Cabinet Under Sink 7. Commode 8. Tub/Fixture 9. Shower/Fixture 10 . Door Stops 11. Towel Bars 12. Window 13. Blinds/Drapes 14. Outlet/Switch Covers 15 . Light Fixtures 16 . Exhaust Fan 17. Other

18 . Smoke Alarm

Observed Not Applicable Attention Needed Bathroom 3

7/14/2016 5:19 PM 1



Overview

7/14/2016 5:19 PM 3



Ceiling

6 7/14/2016 5:20 PM



Cabinet Under Sink

2

7/14/2016 5:19 PM



Flooring

7/14/2016 5:20 PM 5



Sink/Faucet

7 7/14/2016 5:39 PM



Commode

Bathroom 3 Observed Not Applicable Attention Needed

9 7/14/2016 5:20 PM



Shower/Fixture

Bathroom 4	Observed	Not Applicable	Attention Needed
1 . Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Sink/Faucet			
6. Cabinet Under Sink			
7. Commode			
8 . Tub/Fixture			
9 . Shower/Fixture		N/A	
10 . Door Stops			
11. Towel Bars			
12. Window		N/A	
13 . Blinds/Drapes		N/A	
14 . Outlet/Switch Covers			
15 . Light Fixtures			
16 . Exhaust Fan			
17. Other		N/A	

Attention Needed

Bathroom 4 Observed Not Applicable

18 . Smoke Alarm

7/14/2016 5:28 PM



2 7/14/2016 5:28 PM



Overview

1

3 7/14/2016 5:29 PM



Flooring

5 7/14/2016 5:29 PM



Ceiling



Sink/Faucet

7/14/2016 5:29 PM

Bathroom 4 Observed Not Applicable Attention Needed

7

6 7/14/2016 5:29 PM



Cabinet Under Sink

8 7/14/2016 5:29 PM



Tub/Fixture



Commode

Bedroom 2	Observed	Not Applicable	Attention Needed
1 . Overview			
2 . Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops			
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			

OnSight PROS Report

8027 Stalemate Cove, San Antonio, Tx 78254

Attention Needed

Not Applicable

Observed

9 . Light Fixture

10 . Ceiling Fan

11. Closets

12. Other

13 . Smoke Alarm

SMOKE ALARM TEST: Pass ALARM TYPE: Wired

MANUFACTURE DATE: June 2015

7/14/2016 5:01 PM

2 7/14/2016 5:01 PM



Overview

1

3 7/14/2016 5:01 PM




Ceiling



Flooring

4 7/14/2016 5:01 PM



Walls/Paint

7/14/2016 5:01 PM

Observed Not Applicable Attention Needed Bedroom 2

4

7/14/2016 5:01 PM 4



Walls/Paint

7/14/2016 5:01 PM 4



Walls/Paint



Walls/Paint

7/14/2016 5:02 PM 13



Smoke Alarm

Bedroom 3	Observed	Not Applicable	Attention Needed
1 . Overview			
2 . Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops			
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			

OnSight PROS Report

8027 Stalemate Cove, San Antonio, Tx 78254

Bedroom 3

- 9. Light Fixture
- 10. Ceiling Fan
- 11. Closets
- 12. Other
- 13 . Smoke Alarm

SMOKE ALARM TEST: Pass ALARM TYPE: Wired

MANUFACTURE DATE: June 2015

7/14/2016 5:23 PM



2 7/14/2016 5:23 PM



Overview

1

3 7/14/2016 5:23 PM




Ceiling



Flooring

4 7/14/2016 5:23 PM



Walls/Paint

Bedroom 3 Observed Not Applicable Attention Needed

4 7/14/2016 5:23 PM



Walls/Paint

4 7/14/2016 5:23 PM



Walls/Paint

4 7/14/2016 5:23 PM



Walls/Paint

13 7/14/2016 5:24 PM



Smoke Alarm

Bedroom 4	Observed	Not Applicable	Attention Needed
1. Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops			
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			

OnSight PROS Report

8027 Stalemate Cove, San Antonio, Tx 78254

Attention Needed

Not Applicable

Bedroom 4

- 9. Light Fixture
- 10. Ceiling Fan
- 11. Closets
- 12. Other
- 13 . Smoke Alarm

SMOKE ALARM TEST: Pass ALARM TYPE: Wired

MANUFACTURE DATE: June 2015

7/14/2016 5:25 PM **2** 7/14/2016 5:25 PM

Observed



Overview

1

3 7/14/2016 5:25 PM



Ceiling



Flooring

4 7/14/2016 5:25 PM



Walls/Paint

7/14/2016 5:26 PM

Bedroom 4 Observed Not Applicable Attention Needed

4

4 7/14/2016 5:26 PM



Walls/Paint

4 7/14/2016 5:26 PM



Walls/Paint



Walls/Paint

13 7/14/2016 5:26 PM



Smoke Alarm

Bedroom 5	Observed	Not Applicable	Attention Needed
1 . Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops			
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			

OnSight PROS Report

8027 Stalemate Cove, San Antonio, Tx 78254

Attention Needed

Not Applicable

Observed

Bedroom 5

- 9. Light Fixture
- 10. Ceiling Fan
- 11. Closets
- 12. Other
- 13 . Smoke Alarm

SMOKE ALARM TEST: Pass ALARM TYPE: Wired

MANUFACTURE DATE: June 2015

7/14/2016 5:27 PM **2**

2 7/14/2016 5:27 PM



Overview

1

3 7/14/2016 5:27 PM



Ceiling



Flooring

4 7/14/2016 5:27 PM



Walls/Paint

Bedroom 5 Observed Not Applicable Attention Needed

4 7/14/2016 5:27 PM



Walls/Paint

4 7/14/2016 5:27 PM



Walls/Paint

4

7/14/2016 5:27 PM

Walls/Paint

13 7/14/2016 5:28 PM



Smoke Alarm

Bedroom Master	Observed	Not Applicable	Attention Needed
1 . Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Door Stops			
6. Windows			
7. Blinds/Drapes			
8 . Outlet/Switch Covers			

Not Applicable

Bedroom Master

9. Light Fixture

10. Ceiling Fan

11. Closet

12. Other

13 . Smoke Alarm

7/14/2016 5:33 PM



Observed






Attention Needed



Overview

1

3 7/14/2016 5:34 PM



Ceiling



Flooring

4 7/14/2016 5:34 PM



Walls/Paint

Bedroom Master Observed Not Applicable Attention Needed

4 7/14/2016 5:34 PM



Walls/Paint

4 7/14/2016 5:34 PM



Walls/Paint

4 7/14/2016 5:34 PM



Walls/Paint

12 7/14/2016 5:34 PM



Other - Sitting Room

Bathroom Master	Observed	Not Applicable	Attention Needed
1. Overview			
2 . Flooring			
3. Ceiling			
4. Walls/Paint			
5 . Sink/Faucet			
6. Cabinet Under Sink			
7. Commode			
8 . Tub/Fixture			

1

Bathroom Master Observed Not Applicable Attention Needed 9 . Shower/Fixture ✓ □ □ 10 . Door Stops ✓ □ □ 11 . Towel Bars ✓ □ □ 12 . Window ✓ □ □ 13 . Blinds/Drapes ✓ □ □ 14 . Outlet/Switch Covers ✓ □ □ 15 . Light Fixtures ✓ □ □ 16 . Exhaust Fan ✓ □ □ 17 . Other □ N/A □ 18 . Smoke Alarm N/A □

2

7/14/2016 5:35 PM

Overview Flooring

7/14/2016 5:35 PM

Bathroom Master Observed Not Applicable Attention Needed


5

3 7/14/2016 5:35 PM



Ceiling

5 7/14/2016 5:35 PM



Sink/Faucet

6 7/14/2016 5:36 PM



Cabinet Under Sink

7/14/2016 5:35 PM



Sink/Faucet

6 7/14/2016 5:36 PM



Cabinet Under Sink

7 7/14/2016 5:36 PM



Commode

Bathroom Master Observed Not Applicable Attention Needed

8 7/14/2016 5:36 PM **9** 7/14/2016 5:36 PM





Tub/Fixture Shower/Fixture

Utility Room	Observed	Not Applicable	Attention Needed
1. Overview			
2 . Flooring			
3. Ceiling			
4. Walls/Paint			
5. Washer Connection			
6. Washing Machine			
7. Dryer			
8 . Door Stops		N/A	
9. Window			
10 . Blinds/Drapes			
11 . Outlet/Switch Covers			
12 . Light Fixtures			
13. Other		N/A	
14 . Smoke Alarm		N/A	

7/14/2016 5:13 PM

Utility Room Observed Not Applicable Attention Needed

2

1 7/14/2016 5:13 PM



Overview

3 7/14/2016 5:13 PM



Ceiling

6 7/14/2016 5:14 PM



Washing Machine



Flooring

5 7/14/2016 5:13 PM



Washer Connection

6 7/14/2016 5:14 PM



Washing Machine

 Utility Room
 Observed
 Not Applicable
 Attention Needed

7 7/14/2016 5:14 PM





Dryer Dryer

Observed	Not Applicable	Attention Needed
	N/A	
	N/A	
	N/A	
	N/A	
	Observed Observed	N/A

N/A

Miscellaneous Observed Not Applicable Attention Needed

17. Other

1 7/14/2016 5:03 PM



Air Conditioner

9 7/14/2016 5:30 PM



Water Heater

9 7/14/2016 5:30 PM



Water Heater

END OF PROPERTY DETAIL

End of Report